



ESSENTRA

COMPONENTS

December 2, 2020

To whom it may concern:

This letter is to notify you of a part change that Essentra Components has made. This part number replacement was done to consolidate two equivalent parts down to one after Essentra Components

<u>Old Part #</u>	<u>New Part #</u>
NSS-4-10-01	010440P062
NSS-4-12-01	010440P075
NSS-4-14-01	010440P087
NSS-4-16-01	010440P100
NSS-4-2-01	010440P012
NSS-4-3-01	010440P018
NSS-4-4-01	010440P025
NSS-4-5-01	010440P031
NSS-4-6-01	010440P037
NSS-4-7-01	010440P043
NSS-4-8-01	010440P050
NSS-6-10-01	010632P062
NSS-6-12-01	010632P075
NSS-6-14-01	010632P087
NSS-6-16-01	010632P100
NSS-6-2-01	010632P012
NSS-6-3-01	010632P018
NSS-6-4-01	010632P025
NSS-6-5-01	010632P031
NSS-6-6-01	010632P037
NSS-6-7-01	010632P043
NSS-6-8-01	010632P050
NSS-8-10-01	010832P062
NSS-8-12-01	010832P075
NSS-8-14-01	010832P087
NSS-8-16-01	010832P100
NSS-8-2-01	010832P012
NSS-8-3-01	010832P018
NSS-8-4-01	010832P025
NSS-8-5-01	010832P031
NSS-8-6-01	010832P037
NSS-8-7-01	010832P043
NSS-8-8-01	010832P050

Please let me know if you have any questions.

Best Regards,



Greg P. Mifsud

Director of Product Management

ESSENTRA COMPONENTS
3123 Station Road
Erie, PA 16510
United States of America

T (800) 899-9440

F (814) 899-2586

E saleserie@essentracomponents.com

www.essentracomponents.com